



## **CDS G3 2020 v2    9/24/2020**

---

### **New Features**

---

- A new reflash package is available for 3.4L V6 engines.
- A new reflash package is available for 450 Racing.

### **Module Support**

---

- Added support for vessels with single engine electric steering.
- Added support for 5-6 engine DTS vessels.
- Added support for Racing 360 APX engines.

### **Resolved Issues**

---

- Fixed ebom matching issues for Axius systems with VSL-adjusted TVM City Ids.

### **Known Issues**

---

- Disconnecting the Power Steering Pump and connecting back to the boat from the Power Steering Pump screen may generate faults.

**Workaround:**

Return to the main G3 screen before disconnecting the pump and connecting to the boat.

- Starboard and Port DTS Command Modules may fail to reprogram on triple, quad or multi-helm vessels.

**Workaround:**

To prevent programming failures, key on only the module you want to reprogram. Once that module has been successfully reprogrammed, key that location off and move on to the next.

If a module failed to program previously, turn all keys off and remove battery power from the system.

Reapply battery power after 30 seconds and try again following the process above.

- All diagnostic tests will report hardware error once any test has failed for any reason.

**Workaround:**

Key off the affected engine, place the lever in RWOT, and key up to reset diagnostic tests.

- Clicking Reload Engines after keying off a conflicted engine does not work on several of the Diagnostic screens.

**Workaround:**

Exit and reopen the test with one of the engines keyed off.

- Several long standing "Known Issues" have been relocated to our support Web Site.

**Workaround:**

These can be accessed at [service.mercurymarine.com](http://service.mercurymarine.com)

**CDS G3 2020 v1 8/20/2020**

---

- **Fixed:** Fixed issue with VSL importing tool.

**CDS G3 2020 v0 8/12/2020**

---

- Improved application security.