



## **CDS G3 2020 v6    04/12/2021**

---

### **Module Support**

---

- Added support for 3 Cylinder outboard engine vessels.

### **Resolved Issues**

---

- Enabled the Manual Drive Alignment feature for L6 Verado configurations.

### **Known Issues**

---

- Disconnecting the Power Steering Pump and connecting back to the boat from the Power Steering Pump screen may generate faults.

**Workaround:**

Return to the main G3 screen before disconnecting the pump and connecting to the boat.

- Starboard and Port DTS Command Modules may fail to reprogram on triple, quad or multi-helm vessels.

**Workaround:**

To prevent programming failures, key on only the module you want to reprogram. Once that module has been successfully reprogrammed, key that location off and move on to the next.

If a module failed to program previously, turn all keys off and remove battery power from the system.

Reapply battery power after 30 seconds and try again following the process above.

- All diagnostic tests will report hardware error once any test has failed for any reason.

**Workaround:**

Key off the affected engine, place the lever in RWOT, and key up to reset diagnostic tests.

- Clicking Reload Engines after keying off a conflicted engine does not work on several of the Diagnostic screens.

**Workaround:**

Exit and reopen the test with one of the engines keyed off.

- Several long standing "Known Issues" have been relocated to our support Web Site.

**Workaround:**

These can be accessed at [service.mercurymarine.com](http://service.mercurymarine.com)

## CDS G3 2020 v5 03/25/2021

---

- Added additional items to Live Data and fixed reflash for some small outboard engines.
- **Language:** Added language support for Active Trim.
- Updated the CAN driver.
- Updated support for single lever DTS engines.
- **Fixed:** Fixed missing Configuration list after performing set Tilt/Trim Limits.
- Expanded Active Trim configuration.

## CDS G3 2020 v4 02/04/2021

---

- **Fixed:** Updated the range of serial numbers accepted as valid.
- **Fixed:** Fixed Autopilot track pad detection issues.
- **New:** A new reflash package is available for VesselView Mobile modules.
- Added support for Single Electric Steering and engines with BRZ19MAAB software.
- **Fixed:** Fixed issues with setting Tilt and Trim on several Axius eBOMs.
- **Fixed:** Fixed wrong unit of measure on Block Pressure on some older engines.
- Added support for 450 Racing 5-6 engine DTS vessels.

## CDS G3 2020 v3 10/22/2020

---

- Added support for Bravo 4S drives.
- **New:** A new reflash package is available for 6.2 MerCruiser engines.
- Added support for updated MerCruiser software.

## CDS G3 2020 v2 9/24/2020

---

- Added support for vessels with single engine electric steering.
- Added support for 5-6 engine DTS vessels.
- **New:** A new reflash package is available for 3.4L V6 engines.
- **New:** A new reflash package is available for 450 Racing.
- Added support for Racing 360 APX engines.
- **Fixed:** Fixed ebom matching issues for Axius systems with VSL-adjusted TVM City Ids.

## CDS G3 2020 v1 8/20/2020

---

- **Fixed:** Fixed issue with VSL importing tool.

## CDS G3 2020 v0 8/12/2020

---

- Improved application security.

